

Coated & Solid Endmills

J1 ~ J50



Coated Endmills

Selection Guide	According to Work Materials.....	J 2 - 3
	New Global Standard Endmills.....	J 4 - 6
GSX MILL Series	GSX 20000	J 7 - 11
	GSX 30000	J12-13
Slotted Type	GSXSLT 30000.....	J14
	GSX 40000	J15-19
Anti-Vibration Type	GSXVL 40000.....	J20-21
SSEH MILL Series for Exotic Alloys	SSEHVL 4000W-R / SSEH 4000W-R	J22-24
GS MILL Series	GLM 4000SF/SF-R	J25
Hard Type	GSH 4000/6000/8000SF	J26
Roughing Type	GSRE 4000SF.....	J27
UP MILL Series	SSUP 4000ZX/ZX-R.....	J28-29
AURORA COAT MILL Series	ASM 2000/4000DL / DL-R	J30-31
Standard Type	SSM 2000/4000ZX	J32
Long Type	LSM 2000/4000ZX	J33
Hard Type	LHHM 4000/6000/8000ZX	J34
	EHHM 4000/6000/8000ZX	J34
Fast Helix Type	HSM 2000/3000/4000ZX.....	J35
GSX Mills Ball Type	GSXB 20000	J36
GS Mills Ball Type	GLB 2000SF	J37
Ball Mills "Neo"	SNB 2000ZX	J38-39
AURORA COAT Ball Type	SNB 2000DL	J40

Uncoated Endmills

SSEH MILL Series for Exotic Alloys	SSEHVL 4000-R / SSEH 4000-R.....	J41
Standard Type	SSM 2000/4000.....	J42-43
Long Type	LSM 2000/4000.....	J44
Extra LongType	ELSM 2000/4000	J45
Fast Helix Type	HSM 2000/3000/4000	J46
For Aluminium Cutting	ASM 4000	J47
Straight Flute Ball Type	BSM 2000	J47
SUMIBORON "Helical Master" for Hardened Steel	BNES 1000.....	J48
SUMIBORON "Mould Finish Master" for Hardened Steel	BNBP 2R...4/6.....	J49

Solid Carbide
Endmills